



PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	27210	Date:	20.02.2026
Fleet Number	278		
Hour Meter	3444 hrs		

Machine Serviced	250 <input type="checkbox"/> 500 <input type="checkbox"/> 1000 <input type="checkbox"/>	Service Computer reset <input type="checkbox"/>	Service sticker updated <input type="checkbox"/>
------------------	---	---	--

Service due	3867 hrs
-------------	----------

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	/		Fuel Level	100%	
Cab Guards/Covers	NA		Fuel connectors & pipes	100%	
Lifting eye / points	/		Engine Oil Level	100%	
Cab glass	/		Coolant Level	100%	
Chassis bolts & security	/		Hydraulic fluid level	100%	
Seat secure & fully adjustable	/		Washer fluid level	100%	
Tracks	/		Ad-blue level	100%	
Blade / stabilizers if fitted	NA				
Seat & Seat Belt	/				
Steering if applicable	NA				
Brakes as appropriate	NA				
Bodywork	/				
Operating Controls	/				
Warning Lights	/				
Gauges/Instruments	/				
Railings / boxing ring	/				
Fan & other belts / chains	/				
Fuel cap secured	/				
Lenses & mirrors	/				
Rear & 360° cameras	/				
Horn	/				
Travel alarm	/				
Lights / Beacons	/				
Obvious Leaks	/				
Safety pins & bolts	/				
Floor mats/ Air freshener	/				

Electric	OK	Defect
Cable Connections	/	
General Cleanliness	/	
Battery Security	/	

Other Checks	OK	Defect
Front left wheels	/	
Front right wheels	/	
Rear left wheels	/	
Rear right wheels	/	

Defects / Service Details / Notes
 ALL CHECKS DONE, CLEANED ALL AROUND, GREASES ACCORDING
 ALL IN WORKING ORDER

Engineers name: GABRIEL T1	Signature:
-------------------------------	----------------