



GA1 Fleet Number:

HQH188

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 and Power Regulations 1998

Date of Thorough Examination: 14/02/2022		Date of Report: 14/02/2022		Report number: 6M2200111																
Name and Address of employer for whom the thorough examination was made: M J Hickey Plant, 10 Woodlane Close, Iver Heath, Bucks, SL0 0LT			Address of premises at which the examination was made: Buxted Construction Ltd, Redfields Lane, Church Crookham, Hampshire, GU52 0RF																	
Description and identification of the equipment: Quick Hitch Type: Hill Tefra Quick Hitch Quick Hitch S/N: 79246 Equipment Type: Hitachi ZX135US-6 Excavator ID: HCMDAS50V00100451		Safe Working Load(s): In Accordance with manufacture specification.	Date of manufacture if known: Unknown	Date of last thorough examination: 17/02/2021																
Is this the first examination after installation or assembly at a new site or location? <table border="1"> <tr> <td>YES</td> <td>X</td> <td>NO</td> <td></td> </tr> </table>		YES	X	NO		Was the examination carried out:														
YES	X	NO																		
If the answer to the above question is YES has the equipment been installed correctly? <table border="1"> <tr> <td>YES</td> <td>X</td> <td>NO</td> <td></td> </tr> </table>		YES	X	NO		Within an interval of 6 months ? <table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>X</td> </tr> </table>	YES		NO	X	Within an interval of 12 months? <table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>X</td> </tr> </table>	YES		NO	X	In accordance with an examination scheme? <table border="1"> <tr> <td>YES</td> <td>X</td> <td>NO</td> <td></td> </tr> </table>	YES	X	NO	
YES	X	NO																		
YES		NO	X																	
YES		NO	X																	
YES	X	NO																		
		After the occurrence of exceptional circumstances? <table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>X</td> </tr> </table>	YES		NO	X														
YES		NO	X																	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) None Found.																				
Is the above an existing or imminent danger to persons *Note -This is a reportable defect				YES	X															
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) N/A				YES by:																
Particulars of any repair, renewal or alteration required to remedy the defect identified above: Equipment was found to be in safe working order at time of inspection.																				
Particulars of any tests carried out as part of the examination: (If none state NONE) None.																				

Observations / additional comments relative to this thorough examination:
Equipment was found to be in safe working order at time of inspection.

IS THIS EQUIPMENT SAFE TO OPERATE?			YES	X	NO
Name & Qualifications of person making this report: James Walsh City & Guilds, CITB	Name of person signing or authenticating this report on behalf of the author: Signature: <i>Mr James Walsh</i>	Latest date by which next thorough examination must be carried out: 13/08/2022			
Name and address of employer of persons making and authenticating this report: Walsh Plant Ltd, Unit 3 Birchwood Industrial Estate, Hoe Lane, Nazeing, EN9 2RJ					