



PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	24135-7	Date:	14.04.2025
Fleet Number	292		
Hour Meter	445 hrs		

Machine Serviced	250 <input type="checkbox"/>	500 <input type="checkbox"/>	1000 <input type="checkbox"/>	Service Computer reset <input type="checkbox"/>	Service sticker updated <input type="checkbox"/>
------------------	------------------------------	------------------------------	-------------------------------	---	--

Service due	500 hrs
-------------	---------

Plant item	OK	Defect
Rams / bushings	/	
Cab Guards/Covers	h1A	
Lifting eye / points	/	
Cab glass	/	
Chassis bolts & security	/	
Seat secure & fully adjustable	/	
Tracks	/	
Blade / stabilizers if fitted	h1A	
Seat & Seat Belt	/	
Steering if applicable	h1A	
Brakes as appropriate	h1A	
Bodywork	/	
Operating Controls	/	
Warning Lights	/	
Gauges/Instruments	/	
Railings / boxing ring	/	
Fan & other belts / chains	/	
Fuel cap secured	/	
Lenses & mirrors	/	
Rear & 360° cameras	/	
Horn	/	
Travel alarm	/	
Lights / Beacons	/	
Obvious Leaks	/	
Safety pins & bolts	/	
Floor mats/ Air freshener	/	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	100%	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	100%	

Electric	OK	Defect
Cable Connections	/	
General Cleanliness	/	
Battery Security	/	

Other Checks	OK	Defect
Front left wheels	/	
Front right wheels	/	
Rear left wheels	/	
Rear right wheels	/	

Defects / Service Details / Notes  
 ALL CHECKS DONE, CLEANED AROUND, GREASED AROUND ALL IN WORKING ORDER

Engineers name: GABRIEL R. ADRIAN	Signature: 
--------------------------------------	----------------